

Danger

EM02 [WAF-0271] SSGTG #2 INTAKE 27JAN21(00)

SYSTEM OR COMPONENT

LINE ITEM SHEET
ENG-DANGER-2020

Page 1 of 1

2 GTG INTAKES

REMOVE AND INSTALL NEW GASKET IN COMPARTMENT 01-260-1-Q.

REASON FOR TAG-OUT

F-0271

PERSONNEL/EQUIPMENT HAZARDS INVOLVED

FOD

WORK NECESSARY TO CLEAR TAG(S) (INCLUDING TESTS)

REMOVE AND INSTALL NEW GASKET IN COMPARTMENT 01-260-1-Q AND RETURN EQUIPMENT TO LAY UP CONDITION

APPLICABLE DOCUMENTATION (I.E., JOB ORDER, RIP-OUT, S/P, ETC.)	DATE/TIME ISSUED OR ADDED	PETTY OFFICER IN-CHARGE	ACCURACY/ADEQUACY CHECK	REPAIR ACTIVITY REP. (WORK COMPLETE) (WHEN APPROPRIATE)
		CROSS CHECK (WHEN REQ.)	REP. ACT. REP. (WHEN APP.)	
		SECOND PERSON	AUTH. OFFICER (ISSUED)	
		CROSS CHECK (WHEN REQ.)	AUTH. OFFICER (HUNG)	
SEE REASON BLOCK	27-JAN-21 1342	GSM3 CRESPO, CHRISTOPHER 27-JAN-21		
			KELVIN BUJE 27-JAN-21 1327	
		GSM3 Roberts, Austin 27-JAN-21 1035	GSM1 Proetam, Anita 27-JAN-21 1342	

Tag	Status	RA Required (# Line Items)	RA Witness (Initial)	COMPONENT	LOCATION	POSITION
9680		Yes (14)	KLB	GSA-V-3	4-254-0-E	SHUT
9673		Yes (16)	KLB	AHP-V-146	4-254-0-E	SHUT
9681		Yes (10)	KLB	GBA2-V-4	4-254-0-E	SHUT
9908	*	Yes (1)	KLB	NR 2 GTG BLOW IN CONTROL	4-254-0-E	OPEN
9572		Yes (14)	KLB	GFS2-V-3	4-254-0-E	SHUT

* - Tag is to be hung on this line item
+ - Tag is issued on a previous line item
and is not yet reported hung

US000194